



KENYATTA UNIVERSITY
UNIVERSITY EXAMINATIONS 2011/2012
SECOND SEMESTER EXAMINATION FOR THE DEGREE OF BACHELOR
OF SCIENCE (COMPUTER ENGINEERING)
SCE 435: ROBOTS

DATE: Tuesday, 17th April, 2012

TIME: 8.00 a.m. – 10.00 a.m.

INSTRUCTIONS:

Answer question ONE and any TWO of the remaining FOUR questions
All workings should be shown in a neat and legible manner

Question 1 – Compulsory (30 marks)

- a) With regard to control systems, what is the meaning of the following terms?
 - (i) Control inputs (1 mark)
 - (ii) Disturbance inputs (1 mark)
- b) Give five (5) justifications for the use of robots. (5 marks)
- c) Define Direct Numerical Control (DNC) (1 mark)
- d) Discuss the two types of DNC systems (4 marks)
- e) With the aid of a suitable block diagram, explain how speed control of a synchronous 3-phase AC servo-motor can be achieved by varying frequency of AC power supply [8 marks]
- f) Starting with the equivalent circuit of a dc motor, show that the system function for an armature controlled DC servo-motor is given by

$$G(s) = \frac{\theta(s)}{E_a(s)} = \frac{K}{s[L_a J s^2 + (L_a b + R_a J)s + R_a b + K K_b]}$$

(10 marks)

Question 2 (20 marks)

- a) Define the term **work envelope** of a robot (1 mark)
- b) With the aid of suitable sketches, illustrate the work envelope of a cylindrical co-ordinate robot (7 marks)
- c) A double-acting hydraulic cylinder has a bore of 100 mm. The rod is 40 mm in diameter and the stroke is 200 mm. The hydraulic cylinder is required to move a load of 10000 Newtons. Given that the pump can deliver a flow rate of $30 \text{ mm}^3/\text{sec}$, calculate the following:
 - (i) System pressure needed to lift the load (3 marks)
 - (ii) The pulling force that the cylinder generates given the same hydraulic pressure (3 marks)
 - (iii) Speed of the outward stroke (2 marks)
 - (iv) Speed of piston retraction (2 marks)
 - (v) Power used in the outward stroke (2 marks)

Question 3 (20 marks)

- a) Describe the nine steps of the LOTOTO procedure [4 marks]
- b) Given the following coordinates, use suitable sketches to illustrate the difference between incremental and absolute machine tool positioning techniques. A(3,0), B (1,2), C(-3,-1), D(0,-5), E(5,-2). [4 marks]
- c) The part drawing of a component is shown in figure 1 below. Three holes (**A**, **B** and **E**) of 12.5 mm diameter and two holes (**C** and **D**) of 6 mm diameter are to be drilled on the workpiece. The speed and feed rate are 592 rpm and 100 mm/min, respectively. The plate has a thickness of 50 mm. For holes A, B and E, the workpiece should be drilled through while for holes C and D, the workpiece should be drilled to 25 mm depth. Assuming that the spindle is initially at (-25, -25, 0) and absolute positioning is used, write the part program to carry out this operation. G-Codes are provided at the back. [12 marks]





Figure 1

Question 4 (20 marks)

- a) Sketch the response of a second order system to a unit step input for the underdamped condition. On your sketch indicate the following parameters
- Rise time
 - Delay time
 - Maximum overshoot
 - Peak time

(2 marks)

- b) Part of a dynamic system can be modeled as an R-L-C network as given below.



Take v_{in} as the forcing function and v_{out} as the system response. Let $R = 100 \, \Omega$, $L = 800 \, \text{mH}$, $C = 50 \, \mu\text{F}$. Determine the following:

- i. The system function, $H(s)$ [4 marks]
- ii. The static sensitivity of the system [1 mark]
- iii. The undamped natural frequency of the system - ω_n [3 marks]
- iv. The damping ratio of the system - ξ [2 marks]
- v. Maximum overshoot of the system response when the system is subjected to a unit-step input [3 marks]
- vi. Rise time of the system response when the system is subjected to a unit-step input [3 marks]
- vii. Peak time of the system response when the system is subjected to a unit-step input [2 marks]

Question 5 (20 marks)

- a) Compare field control to armature control of dc servo-motors in terms of torque produced and speed ratios achieved (4 marks)
- b) The coolant on a lathe machine should be switched on when the temperature of the work-piece reaches 40°C . An analog temperature sensor is located in the worktable to provide this information. The sensor has an output range of 0 – 10 V and operates linearly in the temperature range 0 to 100°C . The sensor needs to be interfaced to a digital controller such that the controller receives a 5 V signal whenever the temperature is greater than or equal to 40°C and 0 V otherwise.

Design the interface circuit.

***Motivate your design.**

(5 marks)

- c) With the aid of suitable diagrams, show how an incremental rotary encoder can be used to detect speed and direction of rotation of a motor and therefore be able to provide feedback to a digital control system (12 marks)


A basic list of 'G' operation codes is given below. These direct motion of the tool.

G00 - Rapid move (not cutting)
G01 - Linear move
G02 - Clockwise circular motion
G03 - Counterclockwise circular motion
G04 - Dwell
G05 - Pause (for operator intervention)
G08 - Acceleration
G09 - Deceleration
G17 - x-y plane for circular interpolation
G18 - z-x plane for circular interpolation
G19 - y-z plane for circular interpolation
G20 - turning cycle or inch data specification
G21 - thread cutting cycle or metric data specification
G24 - face turning cycle
G25 - wait for input to go low
G26 - wait for input to go high
G28 - return to reference point
G29 - return from reference point
G31 - Stop on input
G33-35 - thread cutting functions
G35 - wait for input to go low
G36 - wait for input to go high
G40 - cutter compensation cancel
G41 - cutter compensation to the left
G42 - cutter compensation to the right
G43 - tool length compensation, positive
G44 - tool length compensation, negative
G50 - Preset position
G70 - set inch based units or finishing cycle
G71 - set metric units or stock removal
G72 - indicate finishing cycle
G72 - 3D circular interpolation clockwise
G73 - turning cycle contour
G73 - 3D circular interpolation counter clockwise
G74 - facing cycle contour
G74.1 - disable 360 deg arcs
G75 - pattern repeating
G75.1 - enable 360 degree arcs
G76 - deep hole drilling, cut cycle in z-axis
G77 - cut-in cycle in x-axis
G78 - multiple threading cycle
G79 - fixed cycle cancel
G81-89 - fixed cycles specified by machine tool manufacturers
G81 - drilling cycle
G82 - straight drilling cycle with dwell
G83 - drilling cycle
G83 - peck drilling cycle
G84 - tapping cycle
G85 - reaming cycle
G85 - boring cycle
G86 - boring with spindle off and dwell cycle
G89 - boring cycle with dwell
G90 - absolute dimension program
G91 - incremental dimensions
G92 - Spindle speed limit
G93 - Coordinate system setting
G94 - Feed rate in ipm
G95 - Feed rate in ipr

G96 - Surface cutting speed
G97 - Rotational speed rpm
G98 - withdraw the tool to the starting point or feed per minute
G99 - withdraw the tool to a safe plane or feed per revolution
G101 - Spline interpolation

M-Codes control machine functions.

M00 - program stop
M01 - optional stop using stop button
M02 - end of program
M03 - spindle on CW
M04 - spindle on CCW
M05 - spindle off
M06 - tool change
M07 - flood with coolant
M08 - mist with coolant
M08 - turn on accessory (e.g. AC power outlet)
M09 - coolant off
M09 - turn off accessory
M10 - turn on accessory
M11 - turn off accessory or tool change
M17 - subroutine end
M20 - tailstock back
M20 - Chain to next program
M21 - tailstock forward
M22 - Write current position to data file
M25 - open chuck
M25 - set output #1 off
M26 - close chuck
M26 - set output #1 on
M30 - end of tape (rewind)
M35 - set output #2 off
M36 - set output #2 on
M38 - put stepper motors on low power standby
M47 - restart a program continuously, or a fixed number of times
M71 - puff blowing on
M72 - puff blowing off
M96 - compensate for rounded external curves
M97 - compensate for sharp external curves
M98 - subprogram call
M99 - return from subprogram, jump instruction
M101 - move x-axis home
M102 - move y-axis home
M103 - move z-axis home



Structure of a block in a part program